


CHANGE PEDAL RETURN SPRING



PARTS INFORMATION:

Description	OLD PART		NEW PART		INTER-CHANGEABILITY Old/New	Effective D.D.
	OLD P/N	REMARKS	NEW P/N	REMARKS		
Change pedal return spring	Not Available	42-44mm	92083-021	41-43mm		Engine No. Z1E-04921

O = interchangeable X = not interchangeable □ = not available

WARRANTY INFORMATION:

If the change pedal return spring is the source of a shifting problem, replace or modify it using Job Code C045 (1.2 hrs.) ■